

WEST MALLING PARISH COUNCIL

MINUTES OF A MEETING OF THE HIGHWAYS, TRANSPORTATION & STREETLIGHTING COMMITTEE HELD ON 15 AUGUST 2016, 7.30PM AT 9 HIGH STREET, WEST MALLING

Present: Mr S Harriott (Chairman)
Mr R Selkirk
Co-opted member:
Borough Cllr Mrs S Luck

THIS MEETING WAS INQUORATE SO ALL MATTERS WERE SUBJECT TO RATIFICATION AT A SUBSEQUENT MEETING

Minute		Action by	Action taken	Response
16/457	APOLOGIES FOR ABSENCE were received from Mr Bullard and Mrs Dean			
16/458	DECLARATIONS OF INTEREST – none other than those routinely declared			
16/459	MINUTES of the meeting held on 20 June 2016 were received. These draft minutes had been circulated to members but could not be approved for signature as the meeting was inquorate. Clerk to note for next meeting.	Clerk		
16/	MATTERS ARISING from the minutes not otherwise on the agenda			
460.1	(16/351.3) Ryarsh Lane – the Clerk was to report again to PROW.	Clerk		
16/	STREETLIGHTING			
461.1	Update – Mr Harriott reported that the order had been placed for Phase 1. Mr Harriott's report is appended to these minutes (Appendix 1) Mr Harriott explained that where there were heritage lights, the replacement would be like-for-like but in other locations a more modern design could be used. Mr Selkirk pointed out that some of the lights in the Conservation Area were not of the heritage design. Mr Harriott and Mr Selkirk would inspect the lights outside of the meeting			
461.2	Budget – Mr Harriott reported that the budget was £34,000 but as the main WMPC budget was in deficit caution would be needed. Mr Harriott suggested that possibly some of the items in Phase 2 might be removed. Mr Harriott suggested that possibly Phase 3 might be carried out in the next financial year.			
461.3	Swan Street – it was agreed that the replacement column 67 in Swan Street be carried out. Mr Selkirk suggested that this ought to be the heritage style. Mr Harriott to contact Mr Bonner.	SH		
16/462	T&MBC PARKING Mr Selkirk reported that the update was still awaited from T&MBC. Double Yellow Lines – response awaited from Mr Robert Styles together with Safety			

	Assessment. Parking Permits – introduced by T&MBC today (15 August 2016). During the first week of the implementation, T&MBC would issue just warning notices.			
16/ 463	<u>SPEEDWATCH</u> Mr Selkirk reported in his e-mail of 10 August 2016 <ul style="list-style-type: none"> • Training will be going over then to an online interactive session that can be done from any PC, laptop etc. Test at the end. • 'Scheme Leaders' will then do some equipment training. Keith was ours, so we will need to get a new one & get them trained on the equipment. • This means we should be able to train new people quicker. • He [Alan] also did the Risk Assessment for Offham Road and we have agreed 2 locations for carrying out speed checks. He will write it up and send it through. 			
16/ 464	<u>NOTICEBOARDS & FINGERPOSTS</u> Mr Selkirk reported that he would provide updated costs for the fingerposts. Mr Selkirk was working on the planning application.			
16/ 465	<u>ROAD SAFETY WEEK</u> It was noted that WMPC had signed up for Road Safety Week November 2016.			
16/ 466	<u>KCC LOCAL TRANSPORT PLAN</u> Members were invited to consider a response to Transport Plan 4: Delivering Growth without Gridlock 2016-2031 (LTP4) Consultation draft is now available at: www.kent.gov.uk/localtransportplan . The consultation deadline is 30 October 2016. You can either fill in the online questionnaire or complete a hard copy and send it to: Transport Strategy Team, Planning and Environment Division, Kent County Council, Invicta House, County Hall, Maidstone, Kent ME14 1XX. KALC will also be responding to the consultation and will aim to finalise its response in early October.			
	Mr Harriott agreed to draft a response to the consultation.		SH	
	Clerk to note for next meeting.		Clerk	
16/ 467	<u>JUNCTION 4 OF M20</u> Receipt was noted of the newsletter http://www.kent.gov.uk/_data/assets/pdf_file/0004/58801/M20-junction-4-eastern-overbridge-scheme-newsletter-3.pdf			
16/ 468	<u>KCC ACTIVE TRAVEL STRATEGY</u> Draft comments had been formulated by Mr Selkirk and submitted by Clerk on behalf of WMPC. This action was ratified.			
16/ 469	<u>QUESTIONS FROM MEMBERS OF THE PUBLIC AND COUNCILLORS</u> – None Next Meeting of this Committee – it was agreed that this would be on Monday 17 October 2016 @ 9 High Street.			
	There being no further business, the Chairman thanked members for attending and closed the meeting at 8.35pm			

	Signed..... Date.....			
--	------------------------------	--	--	--

APPENDIX 1

Street Lighting Planned Maintenance Update report As at 11 August 2016

1. Introduction

- 1.1 This paper updates the Parish Council on the delivery of the Street Lighting Planned Maintenance programme for 2016-17.
- 1.2 The June 2016 Highways Committee considered the results of the initial survey conducted by Streetlights Ltd which set out a number of Category 1 (emergency) and Category 2 (urgent) repairs which needed to be undertaken.
- 1.3 The Category 1 repairs related mainly to electrical safety issues or where the columns are in a hazardous condition. The Category 2 repairs relate mainly to the need to replace lanterns.

2. Survey

- 2.1 The Streetlights survey has identified a total of 8 lights in the Parish Council's ownership, based on information previously supplied by the Parish council and its earlier contractors.
- 2.2 The schedule produced has identified a possible total of 129 streetlights but Councillors should note the following:

Column	Location	Commentary
20	King Street (Reshape House)	Column Cut down; stump only
23	20 King Street	Light and bracket missing
57	16 Police station Road	Lantern and bracket missing
62	Frog Lane (opposite 18)	Not connected to supply
67	Swan Lane (between columns 109-111)	Stump only
127, 128, 129	King Hill	Not connected to mains

3.

Agreed strategy

Phase 1: 2016-17

- 3.1 The Parish Council agreed to undertake the Category 1 issues relating to electrical safety and other health and safety matters. In addition there were a number of smaller Category 2 issues which were relatively inexpensive to undertake and it made sense to do these in Phase 1. The estimated costs of this Phase were £5,036.75 excl VAT.
- 3.2 This order was placed on 29 June 2016.

STREET LIGHTING					
PHASE 1: EMERGENCY AND MINOR WORKS					
Column	Location	Cat	Works	Price	
1		Cat 2	Install secondary isolation unit/pruning	£190.00	
2		Cat 1	Earthing upgrade	£45.00	
3		Cat 2	Install secondary isolation unit/seal hole in column	£92.50	
4		Cat 2	Install secondary isolation unit/pruning	£110.00	not working
7		Cat 2	Install secondary isolation unit	£65.00	
9		Cat 2	Install secondary isolation unit/pruning	£140.00	
10		Cat 1	Install secondary isolation unit, replace photocell and door;	£203.00	
16		Cat 2	Install secondary isolation unit, replace locking nuts, refix lantern	£105.00	
17		Cat 2	Install secondary isolation unit	£65.00	
18		Cat 1	Install secondary isolation unit/replace photocell	£118.00	
19		Cat 2	Install secondary isolation unit/pruning	£140.00	
27		Cat 2	Seal box	£27.50	
28		Cat 1	Install secondary isolation unit/pruning/Earthing	£185.00	
29		Cat 1	Install secondary isolation unit/replace lock nut/Earthing	£125.00	
34		Cat 1	Install secondary isolation unit, upgrade Earthing and seal cabling	£135.00	
35		Cat 1	Install secondary isolation unit, replace mains fuse carrier	£130.00	not working
36		Cat 1	Install secondary isolation unit, upgrade Earthing, repair hinge and refix lantern	£192.50	
37		Cat 2	Install secondary isolation unit, upgrade Earthing, replace door lock	£120.00	
39		Cat 1	Install secondary isolation unit, upgrade Earthing, pruning, refix lantern	£182.50	
40		Cat 1	Install secondary isolation unit, upgrade Earthing	£110.00	
46		Cat 1	Install secondary isolation unit	£65.00	
47		Cat 1	Replace missing lock nuts, repair hinge and upgrade Earthing	£100.00	
48		Cat 1	Replace Swan neck bracket/pruning	£305.00	
50		Cat 1	Install secondary isolation unit and replace photocell	£118.00	
51		Cat 1	Rewire lantern, seal box, reconfigure cable entry, upgrade Earthing and remove bracket	£125.00	
52		Cat 1	Install protection fro supply, install secondary isolation unit, upgrade Earthing and remove bracket	£165.00	
53		Cat 1	Replace photocell	£53.00	
54		Cat 2	Remove stump and pruning	£100.00	
59		Cat 2	Pruning work required	£45.00	
60		Cat 2	Remove both boxes, install new box	£385.00	
85		Cat 2	Pruning	£125.00	
88		Cat 1	Replace ballast	£61.25	not working
91		Cat 2	Pruning	£105.00	
92		Cat 1	Replace photocell	£53.00	
98		Cat 1	Earthing upgrade	£45.00	
99		Cat 2	Install secondary isolation unit	£65.00	
102		Cat1	Earthing upgrade	£45.00	
109		Cat 1	Replace photocell, install secondary isolation, upgrade Earthing and remove redundant ballast	£190.50	
111		Cat 2	Remove socket, reconfigure wiring and secondary isolation	£75.00	
112		Cat 2	Install secondary isolation unit/pruning	£140.00	
115		Cat 1	Install secondary isolation unit, upgrade Earthing and replace door	£195.00	
119		Cat 2	RTV (return to vertical?)	£120.00	
120		Cat 2	Install secondary isolation unit	£65.00	
TOTAL				£5,036.75	

Progress as at 10 August 2016

3.3 Ken Bonner has reported:

We have nearly completed Phase One, but have had some difficulty getting onto a couple of the columns due to parked vehicles. Our engineer is coming in over the weekend if he can't get on them this week. The only thing outstanding will be the column doors on columns 10 & 115. This is because we have had to get them manufactured and the lead time is longer than anticipated. We have been given a date in September, but I will arrange to get them fitted on arrival and update you accordingly.

3.4 This represents reasonably good progress although we await the invoice with interest.

Phase 2: 2016-17

Columns

3.5 There were a number of Category 1 works where the Contractor was not able to give the Parish Council an estimate. This was because a decision needed to be taken on column designs and a quote needs to be obtained from UKPN for electrical works. Assuming that the cost of each of these items is £2,000 the total budget required will be £16,000. Replacement columns should match the type of columns in the immediate vicinity to maintain the street scene.

3.6 I asked Ken Bonner to provide a quotation for these Phase 2 works and he has responded on 10 August with his estimate of **£12,605.50**. This is below my preliminary estimate set out above of £16,000. The commentary with the quotation says:

*There are a number of issues that I need to make you aware of, so that you can understand how we have arrived at these figures. With regard to the UKPN charges, we have used the figures quoted in their published tariff, including traffic management where required.
 For the replacement of the broken Mains cut-outs we have allowed for excavation, although this may not be necessary.
 We have allowed for the existing Heritage lanterns to be refitted to the new columns, to keep costs down and feel that they can be upgraded at any time afterwards.
 For the side entry lantern replacements we have allowed for our budget priced LED lantern (SL1) which is not dissimilar in appearance to the Cosmo lanterns utilised by the previous contractor.
 As there is not enough space in some of the boxes/columns we have added an LED conversion lamp to the price. This will enable us to remove the redundant control gear and create the space required.*

Phase 2: New Columns				
Column	Location	Cat	Works	Price
13		Cat 1	Replace column+UKPN	£1,884.50
20		Cat 1	Replace column+UKPN	£1,884.50
21		Cat 1	Install secondary isolation unit, upgrade Earthing, fit protective sheath, seal hole in box, replace mains cut out, UKPN	£508
44		Cat 1	New column, pruning, traffic, UKPN	£2,506.00
67		Cat 1	Replace column+UKPN	£2,012.00
73		Cat1	Replace column, road closures and UKPN	£2,441.00
30		Cat1	Install secondary isolation unit/upgrade Earthing, seal cabling/UKPN	£282.50
42		Cat 1	Upgrade Earthing, remove stump, reconfigure mains supply/UKPN	£1,087.00
			TOTAL	£12,605.50

Lanterns

- 3.3 In addition the contractor has identified a number of Cat 1 works where new lanterns are required. In my view we should seek to install wherever possible LED lanterns. I estimated the cost of this element to be in the region of £4,500. The contractor's latest estimate is **£4,109.50**.

Phase 2: New Lanterns/other			
41	Cat 1	Remove bins, replace door, RTV and replace Lantern M	£552.50
43	Cat 1	Replace Lantern M and door lock	£350
56	Cat 1	Replace Lantern M	£295
65	Cat 1	Replace Lantern M	£295
68	Cat 1	Replace lantern	£295
69	Cat 1	Replace lantern	£295
6	Cat 2	Install secondary isolation unit/UKPN	£1,008.00
49	Cat 2	Pruning and UKPN for broken mains cut out	£1,018.00
TOTAL			£4,108.50

Phase 3: 2017-18

- 3.5 The contractor has identified a number of Category 2 repairs or renewals. However we anticipate being invited by the County Council to join their LED replacement contract and it may therefore be worth delaying this work until the KCC contact has been sorted as it may be possible to secure a better price for LED lanterns via this contract. Members will also be aware that we may need to budget for the replacement of the existing streetlight lanterns where LED is not installed. At this stage I have not sought an estimate for this work.

Phase 3 works			
5	Cat 2	Replace lantern M/pruning	tba
11	Cat 2	Replace Lantern M, bracket, box	tba
22	Cat 2	Replace lantern and straiten bracket	tba
23	Cat 2	Install lantern and bracket	tba
24	Cat 2	Replace lantern	tba
25	Cat 2	Replace lantern	tba
31	Cat 2	Replace lantern and box	tba
33	Cat 2	Replace Lantern M	tba
38	Cat 2	SH to check	tba
57	Cat 2	Install replacement lantern and bracket	tba
66	Cat 2	Replace panels or lantern	tba
71	Cat 2	Replace lantern M	tba
72	Cat 2	RTV and replace lantern	tba
74	cat 2	Replace lantern	tba
75	Cat 2	replace lantern	tba
95	Cat 2	Replace panels or lantern	tba
96	Cat 2	Replace panels or lantern	tba
121	cat 2	Replace lantern m and missing lock nut	tba
122	Cat 2	Replace lantern M	tba
125	Cat 2	Repair hinge, replace lantern m and door lock	tba
127	cat 2	remove column	tba
128	cat 2	remove column	tba
129	cat 2	remove column	tba
62		sh to check	
Estimated at £750 each			17250

4. Financial resources

4.1 The Highways Committee budget for 2016-17 includes a total of £34,000:

Maintenance		6000.00
Upgrading of Mercury Lights		10000.00
Repairs/emergency		10000.00
Visual structural inspection		5000.00
One off repairs		3000.00

4.2 The proposed budget breakdown is set out below:

Streetlights proposed budgets		Budget	Predicted	Variance
Maintenance contract [Streetlights]		£4,375.50	4,375.50	£0.00
Breakdowns/repairs	Est	£3,000.00	3,000.00	£0.00
Phase 1 Cat 1/Cat 2 works	Est	£5,036.75	5,036.75	£0.00
Phase 2 Columns/Lanterns	Est	£20,500.00	16,714.00	£3,786.00
Contingency	Est	£1,087.75	1,087.75	£0.00
	Total	£34,000.00	30,214.00	£3,786.00
Highways Budget		£34,000.00		

4.3 Members may also recall that there remains £10,000 in Safeguarded sums for additional Street lighting works.

5. Decision required

5.1 The Parish council is asked to:

1. Issue a 2nd Works Order to undertake the Phase 2 [Category 1 and 2 works) at an estimated cost of £16,714
2. To discuss further the proposed Phase 3 works with the contractor.

Appendix: Street Lighting Schedule

17/06/2016 - West Malling Parish Council														old no
Col.	Road	Location	Gear	Colour	Material	Height	Period	Type	Lamp	Wattage	Cell	Feed	Lantern	old no
1	Brickfields	Opposite No. 37	Column	Silver	Steel	5m	All night	Top entry	Mbfu	80	P42	Live	Ac Ford	7
2	A20 London Road	Junction with Brickfields	Lantern	Silver	Steel	5m	All night	Side entry	Cpo T	60	SS12 HT	Live	Philips SGS451	6
3	A20 London Road	Outside No. 273	Column	Silver	Steel	5m	All night	Top entry	Mbfu	80	P42	Live	Eleco	5
4	A20 London Road	Outside Alban & Halvard	Column	Silver	Steel	5m	All night	Top entry	Mbfu	80	ER4N	Live	Eleco	4
5	A20 London Road	Outside No. 249	Column	Silver	Steel	5m	All night	Top entry	Mbfu	80	P42	Live	Eleco	3
6	A20 London Road	Outside No. 239	Column	Silver	Steel	5m	All night	Top entry	Mbfu	80	P42	Live	Eleco	2
7	A20 London Road	Outside No. 233	Column	Silver	Steel	5m	All night	Top entry	Mbfu	80	P42	Live	Eleco	1
8	Town Hill	Outside The Dene	Lantern	Black	Steel	6m	All night	Post top	Son T	70	Microstar 2000	Live	DW Windsor	120
9	Town Hill	Opposite No. 10	Column	Silver	Steel	5m	All night	Top entry	Mbfu	80	P42	Live	Eleco	119
10	Town Hill	Opposite No. 20	Column	Silver	Steel	5m	All night	Top entry	Son E / I	70	P42	Live	Eleco	118
11	Town Hill	Opposite No. 36	Column	Silver	Steel	5m	All night	Wall mounted (1/e)	Mbfu	80	P42	Live	Ac Ford	117
12	Town Hill	Outside Aston Scott Risk Management	Lantern	Black	Steel	6m	All night	Post top	Cdo TT	70	Microstar 2000	Live	DW Windsor	116
13	Town Hill	Opposite West Malling Garage	Lantern	Black	Steel	5m	All night	Post top	Mbfu	80	P42	Live	Unknown Windsor	115
14	High Street	Opposite 'The Bull Inn' pub	Lantern	Black	Steel	6m	All night	Post top	Son E / I	70	Microstar 2000	Live	DW Windsor	114
15	High Street	Outside No. 3	Lantern	Black	Steel	6m	All night	Post top	Son E / I	70	Microstar 2000	Live	DW Windsor	113
16	High Street	On Pad Thai restaurant	Lantern	Black	Steel	5m	All night	Wall mounted (p/t)	Mbfu	80	P42	Live	Unknown Windsor	112
17	Ryarsch Lane	Outside No. 1	Column	Silver	Steel	5m	All night	Top entry	Mbfu	80	P42	Live	Eleco	94
18	Ryarsch Lane	Outside No. 27	Column	Silver	Steel	5m	All night	Top entry	Mbfu	80	P42	Live	Eleco	95
19	Ryarsch Lane	Outside No. 48	Column	Silver	Steel	5m	All night	Top entry	Mbfu	80	P42	Live	Eleco	96
20	King Street	Opposite Reshape House		Black	Steel									93
21	King Street	On The Therapy Rooms	Column	Black	Steel	5m	All night	Wall mounted (p/t)	Son T	70	P12	Live	Unknown Windsor	92
22	King Street	Opposite No. 12	Lantern	Black	Steel	5m	All night	Wall mounted (p/t)	Son T	70	P5	Live	DW Windsor	91
23	King Street	Pole box on No. 20 but no light												
24	King Street	Opposite No. 30	Lantern	Black	Steel	5m	All night	Wall mounted (p/t)	Son T	70	P5	Live	DW Windsor	90
25	King Street	On No. 35 'Coach House'	Lantern	Black	Steel	5m	All night	Wall mounted (p/t)	Son E / I	70	Microstar 2000	Live	DW Windsor	89
26	King Street	Outside flats 7-12	Lantern	Black	Steel	5m	All night	Post top	Son T	50	Microstar 2000	Live	MSD Windsor	88
27	King Street	Opposite the toilets	Column	Silver	Steel	5m	All night	Wall mounted (1/e)	Mbfu	80	P42	Live	Ac Ford	87
28	High Street	On K2 Flooring	Column	Black	Steel	5m	All night	Wall mounted (p/t)	Mbfu	80	P42	Live	Unknown Windsor	86
29	High Street	On Danmar Kitchens	Column	Black	Steel	5m	All night	Wall mounted (p/t)	Mbfu	80	P42	Live	Unknown Windsor	85
30	High Street	On the Heart of Kent Hospice	Column	Black	Steel	5m	All night	Wall mounted (p/t)	Mbfu	80	P42	Live	Unknown Windsor	84
31	High Street	Alleyway between No's 50 & 54	Lantern	Black	Steel	5m	All night	Wall mounted (p/t)	Son E / I	70	P12	Live	Kingswood Windsor	
32	High Street	Junction with Swan Street	Lantern	Black	Steel	6m	All night	Post top	Son T	70	Microstar 2000	Live	DW Windsor	83
33	High Street	On The Hungry Guest restaurant	Lantern	Black	Steel	5m	All night	Wall mounted (p/t)	Mbfu	80	P6	Live	Unknown Windsor	82
34	High Street	On Hicks Estate Agents	Column	Black	Steel	5m	All night	Wall mounted (p/t)	Mbfu	80	P42	Live	Unknown Windsor	81
35	High Street	On Andrew Smith Jewellers	Lantern	Black	Steel	5m	All night	Wall mounted (p/t)	Mbfu	80	P42	Live	Unknown Windsor	80
36	High Street	On the 'Five Pointed Star' pub	Column	Black	Steel	5m	All night	Wall mounted (p/t)	Mbfu	80	P42	Live	Unknown Windsor	79
37	High Street	On No. 107	Lantern	Black	Steel	5m	All night	Wall mounted (p/t)	Mbfu	80	P42	Live	Unknown Windsor	78
38	Wickens Place	Only light on the path	Column	Silver	Steel	3m	All night	Pole Bracket (1/e)	Tungsten	60	P42	Live	Ac Ford	
39	High Street	Opposite No. 117	Lantern	Black	Steel	5m	All night	Wall mounted (p/t)	Mbfu	80	P42	Live	Unknown Windsor	77
40	High Street	On No. 127	Column	Black	Steel	5m	All night	Wall mounted (p/t)	Mbfu	80	P42	Live	Unknown Windsor	76
41	High Street	Outside Tudor House	Column	Silver	Steel	5m	All night	Top entry	Mbfu	80	P42	Live	Eleco	75
42	High Street	Outside church entrance on bend	Lantern	Black	Steel	5m	All night	Post top	Son T	50	P12 RE	Live	JW Ltd. Windsor	72
43	High Street	Opposite No. 148	Column	Silver	Steel	5m	All night	Top entry	Mbfu	80	P42	Live	Eleco	74
44	High Street	Merge point with St Leonards Road	Column	Silver	Steel	5m	All night	Top entry	Mbfu	80	P42	Live	Eleco	73
45	St Leonards Street	1st after High Street merge point	Lantern	Black	Steel	5m	All night	Post top	Son T	70	Microstar 2000	Live	DW Windsor	71
46	St Leonards Street	Outside Douces Manor	Lantern	Silver	Cast iron	5m	All night	Side entry	Cpo T	45	SS12 HT	Live	Philips SGS451	70
47	St Leonards Street	1st from Douces Manor	Lantern	Silver	Cast iron	5m	All night	Side entry	Cpo T	45	SS12 HT	Live	Philips SGS451	69
48	St Leonards Street	Opposite the lake, bus stop column	Lantern	Silver	Steel	5m	All night	Side entry	Cpo T	60	SS12 HT	Live	Philips SGS451	68
49	St Leonards Street	Outside No. 115	Lantern	Silver	Steel	5m	All night	Side entry	Cpo T	60	SS12 HT	Live	Philips SGS451	67
50	St Leonards Street	Outside No. 137	Column	Silver	Steel	5m	All night	Top entry	Mbfu	80	P42	Live	Eleco	66
51	St Leonards Street	Outside No. 155	Lantern	Silver	Steel	5m	All night	Wall mounted (s/e)	Cpo T	45	SS12 HT	Live	Philips SGS451	65
52	St Leonards Street	Outside No. 181	Lantern	Silver	Steel	5m	All night	Wall mounted (s/e)	Cpo T	45	SS12 HT	Live	Philips SGS451	64
53	King Hill	Junction with Teston Road	Lantern	Silver	Steel	5m	All night	Side entry	Son T	70	P42	Live	Philips SGS201	57
54	King Hill	1st from Teston Road	Lantern	n/a	Galvanised	5m	All night	Side entry	Cpo T	45	SS12 HT	Live	Philips SGS451	57
55	King Hill	Outside No. 43	Lantern	Silver	Steel	5m	All night	Side entry	Cpo T	60	SS12 HT	Live	Philips SGS451	58
56	King Hill	Adjacent to layby near roundabout	Column	Silver	Steel	5m	All night	Top entry	Mbfu	80	P42	Live	Ac Ford	59
57	Police Station Road	On No. 16		Silver	Steel									103
58	Police Station Road	On No. 28	Lantern	Black	Steel	5m	All night	Wall mounted (p/t)	Son T	50	P12 RE	Live	JW Ltd. Windsor	100
59	Police Station Road	Opposite No. 64	Lantern	Black	Steel	5m	All night	Post top	Son T	50	P12 RE	Live	JW Ltd. Windsor	101
60	Police Station Road	Outside No. 35	Lantern	Black	Steel	5m	All night	Post top	Son T	50	P12 RE	Live	JW Ltd. Windsor	102
61	Police Station Road	In the cut alleyway to Town Hill	Lantern	Silver	Steel	5m	All night	Post top	Son T	50	P12	Live	Philips ME50	105
62	Frog Lane	Opposite No. 18		Silver	Cast iron	5m		Top entry				n/a		
63	Frog Lane	Opposite No. 13	Lantern	Black	Steel	5m	All night	Post top	Son T	50	P12 RE	Live	JW Ltd. Windsor	123
64	Frog Lane	By the railway bridge	Lantern	Black	Steel	5m	All night	Post top	Son T	50	P12 RE	Live	JW Ltd. Windsor	121
65	Frog Lane	Outside No. 31	Column	Silver	Steel	5m	All night	Top entry	Mbfu	80	P42	Live	Ac Ford	104
66	Swan Lane	Junction with Lavenders Road	Lantern	Black	Steel	5m	All night	Post top	Son T	70	P12	Live	Unknown Windsor	111
67	Swan Lane	Between columns 109 & 111		Silver	Steel									110
68	Swan Lane	Opposite Station Road junction	Lantern	Black	Steel	5m	All night	Post top	Cpo T	45	SS12 HT	Live	Philips SGS451	109
69	Lucks Hill	Adjacent to railway bridge	Lantern	n/a	Galvanised	5m	All night	Post top	Cpo T	90	SS12 HT	Live	Philips SGS451	108
70	Lucks Hill	Entrance to Hermatage Farm	Lantern	n/a	Galvanised	5m	All night	Post top	Son T	70	Microstar 2000	Live	Phosco P514 Windsor	107
71	Lucks Hill	Outside the School	Column	Silver	Steel	5m	All night	Top entry	Mbfu	80	P42	Live	Eleco	106
72	Lavenders Road	Opposite junction with Water Lane	Column	Silver	Steel	5m	All night	Top entry	Mbfu	80	P42	Live	Eleco	97
73	Water Lane	Opposite No. 98 'Pilsdon'	Column	Silver	Steel	5m	All night	Top entry	Mbfu	80	P42	Live	Eleco	98
74	Water Lane	Near Old Parsonage Court	Column	Silver	Steel	5m	All night	Top entry	Mbfu	80	P42	Live	Ac Ford	99
75	Water Lane	1st from High Street	Lantern	Black	Steel	6m	All night	Wall mounted (p/t)	Son T	70	P12	Live	Kingswood Windsor	
76	Offham Road	Opposite No. 10	Lantern	Black	Steel	5m	All night	Post top	Son T	50	P42	Live	Unknown Windsor	36
77	Offham Road	Outside No. 13	Lantern	Black	Steel	5m	All night	Post top	Son T	70	P42	Live	Unknown Windsor	37
78	Offham Road	Outside No. 23	Lantern	Black	Steel	5m	All night	Post top	Son T	70	P42	Live	Unknown Windsor	38
79	Offham Road	Outside No. 33	Lantern	Black	Steel	5m	All night	Post top	Son E / I	70	P42	Live	Unknown Windsor	39
80	Offham Road	Outside No. 36	Lantern	Black	Steel	5m	All night	Post top	Son T	70	P42	Live	Unknown Windsor	40
81	Offham Road	Outside No. 42	Lantern	Black	Steel	5m	All night	Post top	Son T	70	P42	Live	Unknown Windsor	41
82	Offham Road	Outside No. 58	Lantern	Black	Steel	5m	All night	Post top	Son T	70	ER4N	Live	Unknown Windsor	42
83	Offham Road	Outside No. 68	Lantern	Black	Steel	5m	All night	Post top	Son T	70	P42	Live	Unknown Windsor	43
84	Offham Road	Opposite Churchfields green	Lantern	Black	Steel	5m	All night	Post top	Son T	70	P42	Live	Unknown Windsor	44
85	Offham Road	Junction with Churchfields	Lantern	Black	Steel	5m	All night	Post top	Son T	70	P42	Live	Unknown Windsor	45
86	Offham Road	Outside No. 80	Lantern	Black	Steel	5m	All night	Post top	Son T	70	P42	Live	Phosco P514 Windsor	46
87	Offham Road	Opposite No. 92	Lantern	Black	Steel	5m	All night	Post top	Son T	70	P42	Live	Unknown Windsor	47
88	Offham Road	Outside No. 86	Lantern	Black	Steel	5m	All night	Post top	Son E / I	70	P42	Live	Unknown Windsor	47(a)
89	Offham Road	Outside No. 96	Lantern	Black	Steel	5m	All night	Post top	Son T	50	S300C	Live	DW Windsor	48
90	Churchfields	Adjacent St Marys Court entrance	Lantern	Black	Steel	5m	All night	Post top	Son T	70	P42	Live	Unknown Windsor	49
91	Churchfields	Rear of the 'Sacred Crow' pub	Lantern	Black	Steel	5m	All night	Post top	Son T	70	P42	Live	Unknown Windsor	50
92	Churchfields	Opposite No. 30	Lantern	Black	Steel	5m	All night	Post top	Son T	70	P42	Live	Unknown Windsor	51
93	Churchfields	Opposite No. 20 Rose cottage	Lantern	Black	Steel	5m	All night	Post top	Son T	70	P42	Live	Unknown Windsor	52
94	Churchfields	Opposite No. 15	Lantern	Black	Steel	5m	All night	Post top	Son T	70	P42	Live	Unknown Windsor	53
95	Churchfields	Opposite No. 5	Lantern	Black	Steel	5m	All night	Post top	Son T	70	P42	Live	Unknown Windsor	54
96	Churchfields	Footpath outside St Marys Centre	Lantern	Black	Steel	5m	All night	Post top	Son T	70	P42	Live	Unknown Windsor	55
97	Churchfields	Footpath to High Street, adj Column 96	Lantern	Black	Steel	5m	All night	Post top	Son T	70	P42	Live	Unknown Windsor	
98	Churchfields	Outside the church	Lantern	Black	Steel	5m	All night	Post top	Cpo T	90	Microstar 2000	Live	Philips SGS451	
99	Fatherwell Avenue	Outside No. 2	Column	Silver	Steel	5m	All night	Top entry	Mbfu	80	P42	Live	Ac Ford	23
100	Fatherwell Avenue	Outside No. 12	Lantern	Silver	Steel	5m	All night	Side entry	Son T	50	P42	Live	Philips ME50	22
101	Fatherwell Avenue	Outside No. 20	Lantern	Silver	Steel	5m	All night	Side entry	Son T	50	P42	Live	Philips SGS203	21
102	Fatherwell Avenue	Outside No. 30	Lantern	Silver	Steel	5m	All night	Side entry	Cpo T	60	SS12 HT	Live	Philips SGS451	20
103	Fatherwell Avenue	Outside No. 40	Lantern	Silver	Steel	5m	All night	Side entry	Son T	50	ER4N	Live	Philips ME50	19
104	Fatherwell Avenue	On junction with Alma Road	Lantern	n/a	Galvanised	5m	All night	Post top	Cpo T	60	SS12 HT	Live	Philips SGS451	18
105	Fatherwell Avenue	Outside No. 31	Lantern	Silver	Steel	5m	All night	Side entry	Son T	50	P42	Live	Philips ME50	17
106	Fatherwell Avenue	Outside No. 44	Lantern	Silver	Steel	5m	All night	Side entry	Son T	50	P42	Live	Philips ME50	16
107	Fatherwell Avenue	Outside No. 50	Lantern	Silver	Steel	5m	All night	Side entry	Son T	50	P42	Live	Philips ME50	15
108	Fatherwell Avenue	Outside No. 56	Lantern	n/a	Galvanised	5m	All night	Post top	Cpo T	60	SS12 HT</			

APPENDIX 2